# **SAFETY DATA SHEET** 214 Clear Table Top / Casting Resin - Part A







Created: 08/30/2015 Reviewed: 02/28/2022

Page: 1

# 1. Product and Company Identification

Product Code: 214-CLEAR

Product Name: 214 Clear Table Top Casting Resin - Part A

Trade Name: 214 Clear Table Top Casting Resin - Part A

**Manufacturer Information** 

Company Name: Epoxy Systems, Inc.

20774 W Pennsylvania Ave

Dunnellon, FL 34431

**Phone Number:** +1 (352) 489-1666

Emergency Contact: PERS (USA) (800) 633-8252

Alternate Emergency Contact: PERS (International) +1 (801)629-0667

Industrial floor coatings.

## 2. Hazards Identification

GHS Classification	Placard	Key word	GHS hazard phrase	
Skin Corrosion/Irritation, Category 2	Exclamation point	Warning	Causes skin irritation	
Serious Eye Damage/Eye Irritation, Category 2B	none	Warning	Causes eye irritation	
Skin Sensitization, Category 1B	Exclamation point	Warning	May cause an allergic skin reaction	
Aquatic Toxicity (Acute), Category 2	none		Toxic to aquatic life	
Aquatic Toxicity (Chronic), Category 2	Pollution		Toxic to aquatic life with long lasting effects	

#### **GHS Hazard Phrases**

H315 - Causes skin irritation.

H320 - Causes eye irritation.

H317 - May cause an allergic skin reaction.

H401 - Toxic to aquatic life.

H411 - Toxic to aquatic life with long lasting effects.

#### **GHS Precaution Phrases**

P202 - Do not handle until all safety precautions have been read and understood.

P280 - Wear protective gloves/protective clothing/eye protection/face protection.

P261 - Avoid breathing dust/mist/vapors/spray.

P262 - Do not get in eyes, on skin, or on clothing.

P362+364 - Take off contaminated clothing and wash it before reuse.

P273 - Avoid release to the environment.

#### **GHS** Response Phrases

P302+352 - IF ON SKIN: Wash with plenty of soap and water. P332+313 - If skin irritation occurs, get medical advice/attention.

P362 - Take off contaminated clothing.

P305+351+338 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P337+313 - If eye irritation persists, get medical advice/attention.

P304+341 - IF INHALED: If breathing is difficult, remove to fresh air and keep at rest in a position comfortable for breathing. P314 - Get medical attention/advice if you feel unwell.

Created: 08/30/2015 Reviewed: 02/28/2022

P301+330+331 - IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. P311 - Call a POISON CENTER or doctor/physician.

P391 - Collect spillage.

## **GHS Storage and Disposal Phrases**

P501 - Dispose of contents/container to local, state, and federal authority requirements.

P404 - Store in a closed container.

## **Potential Health Effects (Acute and Chronic)**

May cause eye irritation. May cause skin irritation. May cause skin sensitization, an allergic reaction, which becomes evident on reexposure to this material.

#### **Inhalation**

May cause respiratory irritation.

#### **Skin Contact**

May cause skin irritation. Allergic reactions are possible.

#### **Eye Contact**

Causes eye irritation.

## Ingestion

May be harmful if swallowed.

## **Recommended Exposure Limits**

Not established.

#### **Medical Conditions Generally Aggravated By Exposure**

Skin disorders, Respiratory disorders, Eye disorders, Skin Allergies.

## **OSHA Regulatory Status:**

This material is classified as hazardous under OSHA regulations.

## 3. Composition/Information on Ingredients

На	zardous Components (Chemical Name)	CAS#	Concentration	
1.	Bisphenol-a based epoxy resin	25068-38-6	75 - 90 %	
2.	Benzenemethanol	100-51-6	5.0 - 15 %	

## 4. First Aid Measures

## **Emergency and First Aid Procedures**

#### In Case of Inhalation

If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. If experiencing respiratory symptoms: Get medical attention immediately.

#### In Case of Skin Contact

In case of contact, immediately wash skin with soap and copious amounts of water. Remove contaminated clothing and shoes. Get medical attention if irritation develops or persists.

## In Case of Eye Contact

In case of contact with eyes, flush with copious amounts of water for at least 15 minutes. Assure adequate flushing by separating the eyelids with fingers. Call a physician.

#### In Case of Ingestion

If swallowed, wash out mouth with water provided person is conscious. Call a physician immediately. Do not induce vomiting. For further assistance, contact your local Poison Control Center.

#### Signs and Symptoms Of Exposure

May cause skin, eye, and respiratory irritation. May cause allergic skin reaction.

# SAFETY DATA SHEET

# 214 Clear Table Top Casting

Page: 3 Created: 08/30/2015 Reviewed: 02/28/2022

## 5. Fire Fighting Measures

Flash Pt: > 200.00 C Method Used: Pensky-Marten Closed Cup

Explosive Limits: LEL: NE UEL: NE

Autoignition Pt: No data available.

## **Fire Fighting Instructions**

As in any fire, wear a self-contained breathing apparatus in pressure-demand, MSHA/NIOSH (approved or equivalent), and full protective gear.

#### **Flammable Properties and Hazards**

Product is not considered a fire hazard. Closed containers may rupture (due to build up in pressure) when exposed to extreme heat.

#### **Hazardous Combustion Products**

Hazardous decomposition products formed under fire conditions. Carbon dioxide, Carbon monoxide.

### **Suitable Extinguishing Media**

Dry chemical, CO2, water spray or regular foam.

## **Unsuitable Extinguishing Media**

Do not use a direct water stream, which may spread fire.

## 6. Accidental Release Measures

#### Steps To Be Taken In Case Material Is Released Or Spilled

PROCEDURE TO BE FOLLOWED IN CASE OF LEAK OR SPILL.

Absorb with sand or vermiculite and place in closed containers for disposal. Ventilate the area.

### **Protective Precautions, Protective Equipment and Emergency Procedures**

Wear respirator, chemical safety goggles, rubber boots, and heavy rubber gloves. Where splashing is possible, full chemically resistant protective clothing, and boots are required.

#### **Environmental Precautions**

Prevent entry into waterways, sewers, basements or confined areas.

## 7. Handling and Storage

#### **Hazard Label Information:**

Avoid contact with skin and eyes. Do not get on skin and clothing. Avoid inhalation of vapor or mist. Store in a closed container.

#### **Precautions To Be Taken in Handling**

Provide adequate ventilation. Do not breathe vapor. Do not get in eyes, on skin or on clothing.

## **Precautions To Be Taken in Storing**

Keep container tightly closed in a dry and well-ventilated place.

#### **Other Precautions**

May cause sensitization by skin contact. Wash thoroughly after handling.

# 8. Exposure Controls/Personal Protection

Hazardous Components (Chemical Name)		CAS # OSHA PEL		ACGIH TLV	Other Limits	
1.	Bisphenol-a based epoxy resin	25068-38-6	No data.	No data.	No data.	
2	Benzenemethanol	100-51-6	No data	No data	No data	

#### **Protective Equipment Summary - Hazard Label Information:**

Neoprene gloves Safety glasses, or goggles. Impervious clothing. Chemical resistant boots

#### **Respiratory Equipment (Specify Type)**

Normally when good engineering controls are used, no respiratory protection is needed. However, if cured product is abraded by sanding or grinding use a NIOSH approved air-purifying respirator. Where risk assessment shows air-purifying respirators are appropriate use a dust mask type N95 (US) or type P1 (EN 143) respirator. A NIOSH/MSHA approved air purifying respirator with an organic vapor cartridge or canister may be permissible under certain circumstances where airborne concentrations are expected to exceed exposure limits. Protection

Page: 4 Created: 08/30/2015 Reviewed: 02/28/2022

provided by air purifying respirators is limited. Use a positive pressure air supplied respirator if there is any potential for an uncontrolled release, exposure levels are not known, or any other circumstances where air purifying respirators may not provide adequate protection.

## **Eye Protection**

Safety glasses, or goggles.

#### **Protective Gloves**

Nitrile rubber and Neoprene are recommended.

### **Other Protective Clothing**

Where splashing is possible, full chemically resistant protective clothing, safety glasses or face shield and boots are required.

## **Engineering Controls (Ventilation etc.)**

Good general ventilation should be sufficient to control airborne levels. Safety shower and eye bath.

## **Work/Hygienic/Maintenance Practices**

Wash contaminated clothing before reuse. Discard contaminated shoes. Wash thoroughly after handling.

### **Environmental Exposure Controls**

Avoid runoff into storm sewers and ditches which lead to waterways. May be hazardous to the environment if released in large quantities.

released in large quantities.				
9. Physical and Chemical Properties				
Physical States:	[ ] Gas [ X ] Liquid [ ] Solid			
Melting Point:	NE			
<b>Boiling Point:</b>	NE			
<b>Decomposition Temperature:</b>	NE			
Autoignition Pt:	No data.			
Flash Pt:	> 200.00 C Method Used: Pensky-Marten Closed Cup			
<b>Explosive Limits:</b>	LEL: NE UEL: NE			
Specific Gravity (Water = 1):	~ 1.127 - 1.151			
Density:	~ 9.4 - 9.6 LB/GL			
Vapor Pressure (vs. Air or mm Hg):	NE			
Vapor Density (vs. Air = 1):	NE			
<b>Evaporation Rate:</b>	NE			
Solubility in Water:	No data.			
Solubility Notes				
Practically insoluble.				
Percent Volatile:	0.0 % by volume.			
VOC / Volume:	NP			
HAP / Volume:	NP			
Saturated Vapor Concentration:	NE			
Appearance and Odor				

Epoxy odor.

Appearance: Liquid. (various pigmented colors)

	<u> </u>			
10. Stability and Reactivity				
10. Glability and Reactivity				
Stability:	Unstable I   Stable I X I			

#### Reactivity

Avoid: acids, alkalis, oxidizing agents.

Page: 5 Created: 08/30/2015 Reviewed: 02/28/2022

#### **Conditions To Avoid - Instability**

Extreme temperatures.

#### **Incompatibility - Materials To Avoid**

Avoid strong acids, bases, and oxidizing agents.

#### **Hazardous Decomposition Or Byproducts**

Thermal decomposition may produce smoke, carbon monoxide, carbon dioxide, Phenolics.

**Possibility of Hazardous** 

Will occur [ ] Will

Will not occur [X]

**Polymerization:** 

#### **Conditions To Avoid - Hazardous Reactions**

Will not undergo hazardous polymerization in normal storage conditions.

## 11. Toxicological Information

## Toxicological Information

May cause sensitization by skin contact.

## **Chronic Toxicological Effects**

Skin sensitization.

### **Irritation or Corrosion**

Skin Irritation. Irritating to eyes.

### **Symptoms related to Toxicological Characteristics**

May cause sensitization by skin contact. May cause redness, rash on skin.

Hazardous Components (Chemical Name)		CAS#	NTP	IARC	ACGIH	OSHA
1.	Bisphenol-a based epoxy resin	25068-38-6	n.a.	n.a.	n.a.	n.a.
2.	Benzenemethanol	100-51-6	n.a.	n.a.	n.a.	n.a.

## 12. Ecological Information

## **General Ecological Information**

Avoid release to the environment. May be hazardous to the environment if released in large quantities.

#### Results of PBT and vPvB assessment

No data available.

#### **Persistence and Degradability**

Not readily biodegradable.

#### **Bioaccumulative Potential**

No data available.

#### **Mobility in Soil**

not reported, unknown.

# 13. Disposal Considerations

#### **Waste Disposal Method**

Incinerate or dispose of unused material, residues and containers in a licensed facility in accordance with all applicable local, state and federal regulations. Do not discharge substance/product into sewage system.

## 14. Transport Information

## LAND TRANSPORT (US DOT)

**DOT Proper Shipping Name** 

(Non-Bulk)

Not Regulated.

(Bulk)

Environmentally hazardous substance, liquid, n.o.s. (Epoxy Resin) MARINE

POLLUTANT.

NOTE: Marine Pollutants - DOT requirements specific to Marine Pollutants do not apply to non-bulk packagings transported by motor vehicles, rail cars or

Page: 6 Created: 08/30/2015 Reviewed: 02/28/2022

aircraft.

**DOT Hazard Class**: 9

DOT Hazard Label: CLASS 9
UN/NA Number: UN3082

Packing Group: III

Precautionary Label Avoid skin and eye contact. May cause eye and skin irritation. May cause skin

sensitization. Wear protective equipment and clothing. Always read MSDS/SDS

before use.

**AIR TRANSPORT (ICAO/IATA)** 

ICAO/IATA Shipping Name (Non-Bulk)

Not Regulated.

(Bulk)

Environmentally hazardous substance, liquid, n.o.s. (Epoxy Resin) MARINE

POLLUTANT.

NOTE: Marine Pollutants - DOT requirements specific to Marine Pollutants do not apply to non-bulk packagings transported by motor vehicles, rail cars or

aircraft.

UN Number: 3082

Hazard Class: 9 - CLASS 9

Packing Group:

MARINE TRANSPORT (IMDG/IMO)

IMDG/IMO Shipping Name Environmentally hazardous substance, liquid, n.o.s. (Epoxy Resin) MARINE

POLLUTANT.

Note: The presence of a shipping description for a particular mode of transport (ocean, air, etc.), does not indicate that the product is packaged suitably for that mode of transport. Shipment compliance is the responsibility of the person

offering the product for transport.

UN Number: 3082

Hazard Class: 9 - CLASS 9

Packing Group:

IMDG MFAG Number:

FA,SF

Marine Pollutant:

Yes

15. Regulatory Information

#### **US EPA SARA Title III**

**Hazardous Components (Chemical Name)** CAS# **Sec.304 RQ** Sec.313 (TRI) Sec.110 Sec.302 (EHS) 1. Bisphenol-a based epoxy resin No 25068-38-6 No No No 2. Benzenemethanol 100-51-6 No No No No

**Regulatory Information** 

SARA Section 311/312: Acute Health Hazard.

Page: 7 Created: 08/30/2015 Reviewed: 02/28/2022

## 16. Other Information

CA=CIRCA NA=NOT AVAILABLE NE=NOT ESTABLISHED NR=NOT REGULATED NP= NOT APPLICABLE PR=PROPRIETARY TS=TRADE SECRET ?=UNKNOWN.

## **Company Policy or Disclaimer**

The information contained in this MSDS is taken from sources believed to be accurate as of the date hereof; however Epoxy Systems, Inc. makes no expressed or implied warranty in respect to the accuracy of the information or the suitability of the recommendations, and assumes no liabilities to any user thereof.

Revision Date: Created: 08/30/2015 Reviewed: 02/28/2022